

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/10/2020

Submitted Date:

04/10/2020

Document Number:

693502669

FIELD INSPECTION FORM
 Loc ID 317959 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240254	WELL	PR	08/01/2017	GW	123-08042	JUST UNIT 1	PR

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Mechanical issue: What appears to be a 1" vlv leaking on well head		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/01/2020
Type	OTHER		
Comment:	Stained soil around well head		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	05/01/2020
Type	DEBRIS		
Comment:	Dead weeds on road, locationa and around electric panel.		
Corrective Action:	Comply with rule 603 f	Date:	04/17/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	square tubing		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240254 Type: WELL API Number: 123-08042 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday April 10, 2020 at approximately 10:45AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Graham Just Unit #1</p> <p>Operator: KP Kauffman</p> <p>API#: 05-123-08042</p> <p>County: Weld</p> <p>While there, I observed Well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds: rule 603f Corrective action date of 4-17-20 see photos 2</p> <p>Stained soil: Rule 907 e Corrective action date of 5-1-20 see photo 3</p> <p>Mechanical issue: Rule 605 d Corrective action date of 5-1-2 see photo 3,</p> <p>Weather conditions: Sunny and location dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/10/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402367961	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120869
693502670	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120866