

**Inspection Photos**  
**Operator: Enduring Resources**  
**API#: 067-07650**  
**Date: 4/14/2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with grasses such as western wheatgrass and sand dropseed.



Photo 3. View of the stained soils (approx. 5 feet wide and 10 feet long) placed in the eastern interim reclamation area.



Photo 4. View of deep rutting (approx. 1.5 ft deep) and evidence of vegetation damage along the access road.



Photo 5. View of reference area, comprised of pinyon-juniper woodland with understory of sagebrush, antelope bitterbrush, and a mixture of grasses and forbs.