

# Inspection Photos

Location Name: GOLDEN EAGLE 21-04

API#: 05-071-08425

INSP. #: 695102714



Colorado Oil & Gas Conservation Commission  
37.12101, -104.93359, 317°  
2020/04/20 12:09:35



Colorado Oil & Gas Conservation Commission  
37.1632, -104.90161, 2349.0m, 335°  
2020/04/20 12:11:07

**PHOTO 1: LOCATION**

**PHOTO 2: WELL SIGN/ POSTED SIGN NOT LEGIBLE. **COMPLY WITH RULE 210.b. CA DATE 6-20-20.****

## Inspection Photos

Location Name: GOLDEN EAGLE 21-04

API#: 05-071-08425

INSP. #: 695102714



### PHOTO 3: APPEARS TO BE FRAC SAND ON LOCATION.

**Immediately comply with material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector. Notify area EPS within 24-hrs and report to other agencies as appropriate. CA DATE 4-30-20.**

### PHOTO 4: APPEARS TO BE FRAC SAND ON LOCATION.

**Immediately comply with material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector. Notify area EPS within 24-hrs and report to other agencies as appropriate. CA DATE 4-30-20.**

## Inspection Photos

Location Name: GOLDEN EAGLE 21-04

API#: 05-071-08425

INSP. #: 695102714



**PHOTO 5: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-25-20.**

**PHOTO 6: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-25-20.**

## Inspection Photos

Location Name: GOLDEN EAGLE 21-04

API#: 05-071-08425

INSP. #: 695102714



**PHOTO 7: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-25-20.**

**PHOTO 8: AREA OF IMPACTED SOIL AROUND ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-25-20.**

## Inspection Photos

Location Name: GOLDEN EAGLE 21-04

API#: 05-071-08425

INSP. #: 695102714



**PHOTO 7: AREA OF IMPACTED SOIL NEAR WELLHEAD APPEARS TO BE FROM HYDRAULIC HOSED. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-25-20.**

**PHOTO 8: AREA OF IMPACTED SOIL NEAR HYRDAULIC HOSED BETWEEN ENGINE SKID AND WELLHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-25-20.**

## Inspection Photos

Location Name: GOLDEN EAGLE 21-04

API#: 05-071-08425

INSP. #: 695102714



**PHOTO 9: STANDING OILY WATER IN ENGINE SKID. Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 5-20-20.**

**PHOTO 10: TWO 1" UNUSED RISERS NEAR COMPRESSOR SKID. COMPLY WITH RULE 603.f. CA DATE 5-20-20.**