

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2020

Submitted Date:

04/20/2020

Document Number:

688800729**FIELD INSPECTION FORM**Loc ID 325963 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215641	WELL	PR	08/01/2019	GW	067-07246	GARCIA 1	EI
475456	SPILL OR RELEASE	AC			-	Garcia 1	EI

General Comment:

On April 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Garcia #1. For the most recent field inspection report of this facility, please refer to document #693900870. This site visit was performed to assess Spill/Release Point ID #475456.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well head has LOTO tags on valves.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label with capacity, contents, and NFPA placard attached to steel ring secondary containment.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Posted on location sign.		
Corrective Action:		Date:	_____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Guard fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panel fencing around separator and meter run.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Perimeter fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment: Telemetry equipment.			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Electrical supply equipment.			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.285090,-107.744820
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity) 95 bbl.	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	215641	Type:	WELL	API Number:	067-07246	Status:	PR	Insp. Status:	EI
Facility ID:	475456	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 52

Comment: [Please see document #402371084 for more information regarding this release.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a.](#)

Date: 05/20/2020

Reportable: YES

GPS: Lat 37.284121

Long -107.744828

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Culverts	Pass			
Berms	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Containment device around stuffing box.
Rip Rap	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On April 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Garcia #1. For the most recent field inspection report of this facility, please refer to document #693900870. This site visit was performed to assess Spill/Release Point ID #475456.</p> <p>The Garcia #1 appears to be shut in until repairs can be made to the gathering line south of the location.</p> <p>Salt staining is apparent along the access road. This continues to the intersection with Mira Sol Drive and flows through the culvert to an impoundment on the east side of the road. Stained vegetation and evidence of flow continue towards the head of the impoundment. No standing water was observed during this inspection.</p>	hughesjo	04/20/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
688800730	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128056