

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/14/2020

Submitted Date:

04/14/2020

Document Number:

696301687

**FIELD INSPECTION FORM**Loc ID 305168 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 70385

Name of Operator: SMITH ENERGY CORP

Address: 12706 SHILOH RD

City: GREELEY State: CO Zip: 80631

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 330-7034	gsmithten@what-wire.com	
Smith, Chris	(970) 330-7034	smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274861	WELL	SI	06/01/2018	OW	123-22590	CHINOOK 1	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unmarked Riser at Gas meter, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	04/17/2020
Type	WEEDS		
Comment:	New weed encroachment observed around entire tank battery, wellhead, location & access road areas. Original Corrective Action Date still applies: 06/20/2019 Refer to Rule 603.f. See photos		
Corrective Action:	Remove, manage, & control weeds around entire tank battery, wellhead, location & access road areas. Comply with Rule 603.f. See photos	Date:	06/20/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Does not appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		40.579250,-103.732090	
Comment:	Maintenance Tank					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	PBV STEEL		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Share berm with the Maintenance Tank				
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 274861 Type: WELL API Number: 123-22590 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [SI. Observed production valves closed.](#)  
[COGCC records indicate last prod: 05/2018.](#)  
[Well is approaching the 2-Year Shut-In MIT per Rule 326.b.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Seeding				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 04/08/2020 at approximately 13:54, I, Inspector Erica Petrie, conducted a Field Inspection at Smith Energy Corp. Chinook #1 at Location #305168 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1 of 1 Corrective Actions appears NOT addressed. 1 new Corrective Action</p> <p>1.) Weed encroachment observed around entire wellsite.</p> <p>Refer to Rule 603.f.</p> <p>Remove, manage, &amp; control weeds around wellsite. Comply with Rule 603.f.</p> <p>Corrective Action date: 06/20/2018.</p> <p>See photos.</p> <p>2.) Unmarked Riser at Gas Meter, see photos. Comply with Rule 603.f. Corrective Action date: 04/17/2020.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petrie	04/14/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402370448	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5123574">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5123574</a>
696301688	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5123570">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5123570</a>