

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2020

Submitted Date:

04/20/2020

Document Number:

699501103

FIELD INSPECTION FORM

Loc ID 320271 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|---------------------------------|
| , | | cogcc@kpk.com | All Inspections |
| Ferrin, Jeremy | | jeremy.ferrin@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 203302 | WELL | PR | 12/01/2019 | OW | 001-08811 | TIPPETT ET AL 6-2 | PR |

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Gas meter run has not been calibrated since 2001

Corrective Action: Measure gas per Rule 329

Date: 05/20/2020

Overall Good:

Spills:

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|-------------|---------|--------|
| PRODUCED WATER | 1 | <50 BBLs | BV CONCRETE | | |

Comment:

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

| | |
|------------------|--|
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|---|
| | | | | |
| Comment: Shares containment with oil tanks | | | | |
| Corrective Action: | | | | Date: <input style="width:100px;" type="text"/> |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|---|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: <input style="width:100px;" type="text"/> |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|---|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: <input style="width:100px;" type="text"/> |

Venting:

| | | |
|--------------------|----|---|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: <input style="width:100px;" type="text"/> |

Flaring:

| | |
|--------------------|---|
| Type | |
| Comment: | |
| Corrective Action: | Date: <input style="width:100px;" type="text"/> |

Inspected FacilitiesFacility ID: 203302 Type: WELL API Number: 001-08811 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On 4/20/20 at approximately 1250 I, Inspector Justin Medina conducted an on-site inspection at KPK- API 001-08811 -Tippett ET AL 6-2 in Adams County Colorado. While there, I observed Producing well</p> <p>This is a follow up inspection</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Gas meter run has not been calibrated since 2001 see pic</p> <p>Measure gas per Rule 329. 5/20/20</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection perception of location may have been distorted due to weather conditions.</p> <p>This is a summary of inspection report.</p> | medinaj | 04/20/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 699501104 | pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128796 |