

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/14/2020

Submitted Date:

04/14/2020

Document Number:

699800907

FIELD INSPECTION FORM

Loc ID 312511 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 12 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@maralexinc.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Jordan, Reid	970-563-4000	maralextechjr@gmail.com	Ignacio

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221818	WELL	SI	09/01/1989	GW	077-08420	FEDERAL 35-2	TA

General Comment:

[COGCC Inspection Report Summary](#)
On Tuesday 4/14/20 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at MARALEX RESOURCES INC FEDERAL-68S98W /35SENW, Location #312511 in Mesa County Colorado.
While there, I observed normal production operations.
During this inspection the following possible compliance issues were observed: Debris inside both pits. See photo #0962 and #0963 with a corrective action date of 4/21/20. Multiple flowline risers not LO/TO. See photo #0964 and #0965 with a corrective action date of 4/15/20. MIT required on well. With a corrective action date of 5/14/20. No pit permit on record for both pits. With a corrective action date of 4/29/20. No netting on pits. See photo #0962 and #0963 with a corrective action date of 4/24/20.

While there I spoke with Jim Graves from Maralex resources. Jim was hooking up a test separator to test the well to see if it was capable of production.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Multiple flowline risers not LO/TO. See photo #0964 and #0965		
Corrective Action:	Flow line risers not LO/TO or marked are considered unused equipment. Properly lock out tag out or plug flow line risers.		Date: <u>04/15/2020</u>
Type	DEBRIS		
Comment:	Debris inside both pits. See photo #0962 and #0963		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove debris from location.		Date: <u>04/21/2020</u>

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	PIT		
Comment:	Hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment:	Test separator mounted on trailer.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 221818 Type: WELL API Number: 077-08420 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well last produced prior to 1999. No MIT on record.

Corrective Action: All temporarily abandoned wells shall pass a mechanical integrity test. Preform MIT on well.

Date: 05/14/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Compaction				
		Gravel				
		Ditches				
Ditches						
Berms						
Compaction						
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown

Lined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: No pit permit on record for both pits.

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information.

Date: 04/29/2020

Fencing:

Fencing Type: Livestock

Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: No netting on pits. See photo #0962 and #0963

Corrective Action

The operator shall take precautions to prevent significant adverse impacts to environment and wildlife resources. Add netting to pits.

Date: 04/24/2020

Anchor Trench Present: _____

Oil Accumulation: NO

2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
<u>No tank battery on location.</u>	depaoloc	04/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402371027	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5124131
699800909	Photos for Insp. #699800907	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5124127