

**Inspection Photos**  
**Location Name: William D Lansdown unit D #1**  
**Location ID: 318987**



**Photo 1 WH sign**




**Photo 2 WH**

**Inspection Photos**  
**Location Name: William D Lansdown unit D #1**  
**Location ID: 318987**




**Photo 3 tree growing under transformer**



**Photo 4 TB sign**

**Inspection Photos**  
**Location Name: William D Lansdown unit D #1**  
**Location ID: 318987**



**Photo 5 TB**



**Photo 6 Gas meter run**



**Location ID: 318987**



**Photo 8 ECD**

**Inspection Photos**  
**Location Name: William D Lansdown unit D #1**  
**Location ID: 318987**




**Photo 9 Horizontal Heated Separator**




**Photo 10 stained soil under separator**

**Inspection Photos**  
**Location Name: William D Lansdown unit D #1**  
**Location ID: 318987**



**Photo 11 stained soil under crude tank valve**



**Photo 12 stained soil by crude tank valve**



**Inspection Photos**  
**Location Name: William D Lansdown unit D #1**  
**Location ID: 318987**



**Photo 13 stained soil under crude tank valve**



**Photo 14 trash in tank berm**