

Inspection Photos

API: 055-06142

Operator: TABULA RASA ENERGY

Inspection Date: 4/22/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 4/22/2020

Inspection Photos



Photo 1. Facing north along the access road which is maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 4/22/2020

Inspection Photos



Photo 2. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 4/22/2020

Inspection Photos



Photo 3. Well sign is posted at the well head. Emergency contact number on the sign needs to be updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 4/22/2020

Inspection Photos



Photo 4. Facing northeast toward the interim reclamation area.



Inspection Photos



Photo 5. There are some noxious weeds along the north side of the location. Arrows points to Common mullein and Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 4/22/2020

Inspection Photos



Photo 6. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 4/22/2020

Inspection Photos



Photo 7. Facing northeast toward well and meter shed. Well sign is posted at the well head. Emergency contact number on the sign needs to be updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 4/22/2020