

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2020

Submitted Date:

04/20/2020

Document Number:

688800729

FIELD INSPECTION FORM

 Loc ID 325963 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 1199 MAIN AVENUE SUITE 101
 City: DURANGO State: CO Zip: 81301
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215641	WELL	PR	08/01/2019	GW	067-07246	GARCIA 1	EI
475456	SPILL OR RELEASE	AC			-	Garcia 1	EI

General Comment:

On April 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Garcia #1. For the most recent field inspection report of this facility, please refer to document #693900870. This site visit was performed to assess Spill/Release Point ID #475456.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well head has LOTO tags on valves.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label with capacity, contents, and NFPA placard attached to steel ring secondary containment.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Perimeter fencing.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panel fencing around separator and meter run.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Guard fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.285090,-107.744820
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215641 Type: WELL API Number: 067-07246 Status: PR Insp. Status: EI

Facility ID: 475456 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 52

Comment: Please see document #402371084 for more information regarding this release.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 05/20/2020

Reportable: YES

GPS: Lat 37.284121

Long -107.744828

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Containment device around stuffing box.
Berms	Pass					
Gravel	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On April 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Garcia #1. For the most recent field inspection report of this facility, please refer to document #693900870. This site visit was performed to assess Spill/Release Point ID #475456.</p> <p>The Garcia #1 appears to be shut in until repairs can be made to the gathering line south of the location.</p> <p>Salt staining is apparent along the access road. This continues to the intersection with Mira Sol Drive and flows through the culvert to an impoundment on the east side of the road. Stained vegetation and evidence of flow continue towards the head of the impoundment. No standing water was observed during this inspection.</p>	hughesjo	04/20/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402375823	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128057
688800730	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128056