

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

696301750

FIELD INSPECTION FORM

Loc ID 443153 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Neighbors, Cory		cneighbors@hpres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443154	WELL	PR	05/01/2016	OW	123-42155	Anschutz Equus Farms 4-62-9-4841C2	PR
443155	WELL	PR	06/01/2016	OW	123-42156	Anschutz Equus Farms 4-62-9-4956C2	PR
443156	WELL	PR	05/01/2016	OW	123-42157	Anschutz Equus Farms 4-62-9-6457C2B	PR
443157	WELL	PR	05/01/2016	OW	123-42158	Anschutz Equus Farms 4-62-9-6457B2B	PR
443158	WELL	PR	05/01/2016	OW	123-42159	Anschutz Equus Farms 4-62-9-4956B2	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Bradenhead	# 5	Comment: Appear to be plumbed to surface			
Type: Gas Meter Run	# 10	Comment:			
Type: Horizontal Heated Separator	# 5	Comment:			
Type: Plunger Lift	# 5	Comment:			

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	443154	Type:	WELL	API Number:	123-42155	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	443155	Type:	WELL	API Number:	123-42156	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	443156	Type:	WELL	API Number:	123-42157	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	443157	Type:	WELL	API Number:	123-42158	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	443158	Type:	WELL	API Number:	123-42159	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection	petrie	04/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301751	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133652