

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

699301546**FIELD INSPECTION FORM**
 Loc ID 333141 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261327	WELL	SI	05/01/2018	GW	123-20577	WALSH 24-24	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Misc. equipment inside AG fence at WH lying on the ground		
Corrective Action:	Comply with Rule 603.f	Date:	05/12/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	AG fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas Meter run- fabricated square tubing		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Automation		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	partially exposed at surface	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with crude tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected FacilitiesFacility ID: 261327 Type: WELL API Number: 123-20577 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since 5-1-2018

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On Monday 4/27/2020 at approximately 1335 hrs. I, Inspector Robbie Revas,
Conducted an on-site inspection at a PDC Energy Location:

Walsh #24-24 at API #05-123-

20577 in Weld County Colorado.

While there, I observed a shut in wellsite and tank battery. SI since 5-1-2018, sign on well shows SI for Horiz. Prep. There has been a form 42 (FLO) Doc # 401370286 submitted on 8-9-2017.

Form 42 (MIT) Doc # 402330015 submitted on 3-3-2020.

Form 42 (MIT) Doc # 402370450 Submitted on 4-14-2020.

During this inspection the following compliance issue was observed:

603.f Housekeeping: Misc. unused equipment lying on ground inside AG fence. CA date 5-12-2020.

See attached photos 2 & 3.

Location is dry, weather is clear.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

Continuing education COGCC Inspection Report Summary.

This is a summary of inspection report.

revasr

04/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301548	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134175