

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

699301544

**FIELD INSPECTION FORM**

Loc ID 333141 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241452	WELL	PR	08/01/2019	GW	123-09241	WALSH 4	PR

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	barbwire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	

**Equipment:**

Type	Equipment	Quantity	Comment	Corrective Action	Date	corrective date
Type: Bradenhead		# 1				
Comment:	appears to be plumbed to surface					
Corrective Action:					Date:	
Type: Ancillary equipment		# 1				
Comment:	electric panel					
Corrective Action:					Date:	
Type: Prime Mover		# 1				
Comment:	electric motor					
Corrective Action:					Date:	
Type: Pump Jack		# 1				
Comment:						
Corrective Action:					Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241452 Type: WELL API Number: 123-09241 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Monday 4/27/2020 at approximately 1310 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman Location:</p> <p style="text-align: right;">Walsh #4 at API #05-123-09241 in Weld County Colorado.</p> <p>While there, I observed a producing wellsite. Location ID is shared with PDC Energy well that has been inspected separately.                      During this inspection the no compliance issues were observed:                      See attached photos.                      Location is dry, weather is clear.                      No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	04/27/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301545	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134174">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134174</a>