

Inspection Photos

API: 043-06215

Operator: WINN EXPLORATION CO INC

Inspection Date: 4/27/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 4/27/2020

Inspection Photos



Photo 1. Facing west toward the location. A gravel pile remains at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 4/27/2020

Inspection Photos



Photo 2. The degraded wattles remain around the eastern perimeter. The degraded wattles and stakes need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 4/27/2020

Inspection Photos



Photo 3. Facing northwest toward the location. Vegetation is progressing throughout the reclamation area but does not appear to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 4/27/2020

Inspection Photos



Photo 4. There is a gravel pile stored at the location causing disturbance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 4/27/2020

Inspection Photos



Photo 5. Facing southwest toward the location. Vegetation appears to be establishing in this area of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 4/27/2020

Inspection Photos



Photo 6. Facing south at the eastern side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 4/27/2020

Inspection Photos



Photo 7. The vegetation observed at the location included Sand dropseed, Blue grama, and Western wheat grass.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 4/27/2020