

Inspection Photos  
Operator: BP America  
API#: 067-06532  
Date: 4/28/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with a mixture of grasses such as smooth brome and sand dropseed, as well as shrubs such as rubber rabbitbrush.



Photo 3. View of Canada thistles within the northern project area. Approximately 50 individuals observed.



Photo 4. View of hoary cress (*Cardaria draba*) within the western project area. Approximately 200 individuals observed.



Photo 5. View of the southern project area from the southeastern corner facing eastward. A steep arroyo runs adjacent to the southern project area. Stormwater erosion appears to be controlled at this time but needs to continue to be monitored.



Photo 6. View of reference area vegetation comprised of open sagebrush shrubland, with understory grasses and forbs such as western wheatgrass, blue grama, sand dropseed, and milkvetch.