

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2020

Submitted Date:

04/30/2020

Document Number:

693700444**FIELD INSPECTION FORM**Loc ID 444342 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neighbors, Cory		cneighbors@hpres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444356	WELL	DG	10/22/2016	LO	123-42580	FOX CREEK 223-3422H	EI
471741	SPILL OR RELEASE	AC			-	FC 34 #222-3422 Frac Water Spill	EI

**General Comment:**[COGCC Environmental Inspection of Spill ID 471741](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
Other	Tank	<= 1 bbl		
Comment:	pump or filter located in secondary containment with oil ASTs is leaking water and oil, pipe fitting to oil tank also leaking.			
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date: 05/15/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	444356	Type:	WELL	API Number:	123-42580	Status:	DG	Insp. Status:	EI
Facility ID:	471741	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Environmental****Spill/Remediation:**

Comment: [COGCC followup to Spill ID 471741 release during fracturing treatment. No surface impacts or soil stockpiles observed.](#)

Corrective Action: [Operator is directed to submit Form 19 Supplemental Report with confirmation soil samples \(ph, EC, SAR, BTEX, TPH \(C6-36\) and site map of impacted area](#) Date: 06/12/2020

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700445	Leaking fitting on AST	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139268">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139268</a>
693700446	Leaking pump in secondary containment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139269">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139269</a>