

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2020

Submitted Date:

04/27/2020

Document Number:

700401231

**FIELD INSPECTION FORM**

Loc ID 315620 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 3975  
Name of Operator: ARGALI EXPLORATION COMPANY  
Address: PO BOX 416  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rector, Brian		brector1983@gmail.com	
Blyster, Brandon		blysteroil@aol.com	
, Argali Exploration Company	970-629-1906	argaliexplorationcompany@gmail.com	
Rector, Jeff		jbrduco@yahoo.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231172	WELL	PR	03/18/1985	GW	103-08841	FEDERAL I-2-3-101	PR

**General Comment:**

On 4-24-2020 inspector Rick Moran conducted a follow up inspection at Argali Exploration well Federal I-2-3-101 in Rio Blanco county of FIR documents:

- 1) 679704833 dated 7-23-2019.
- 2) 679706054 dated 11-12-2019.
- 3) 679706675 dated 12-23-2019.
- 4) 700400357 dated 3-6-2020.

The following compliance issues are uncompleted:

- 1) Well head sign. Photo 2. Complete by 9-20-2019.
- 2) Lease road sign lying on ground. Photo 5. Complete by 1-25-2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700401231.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lease road sign lying on ground.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	01/25/2020
Type	WELLHEAD		
Comment:	No sign present at well head.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	09/20/2019

Emergency Contact Number:			
Comment:	911		Date:
Corrective Action:			_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:			
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 231172 Type: WELL API Number: 103-08841 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment: Separator pit.

Corrective

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife    Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type:    Netting Condition:

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

Anchor Trench Present:                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment: Meter building pit.

Corrective

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife    Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type:    Netting Condition:

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard:
Comment:	<input type="text"/>	
Corrective	<input type="text"/>	
		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402381349	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5132950">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5132950</a>
700401232	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5132945">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5132945</a>