

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2020

Submitted Date:

05/04/2020

Document Number:

693502853

FIELD INSPECTION FORM

Loc ID 320468 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10454

Name of Operator: PETROSHARE CORPORATION

Address: 9635 MAROON CIRCLE #400

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|----------------------------|-----------------|
| GRIMES, MEGHAN | | mgrimes@petrosharecorp.com | Principal Agent |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 256027 | WELL | PR | 06/30/2008 | GW | 001-09396 | GASPAR 11-1 | PR |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | DEBRIS | | |
| Comment: | Dead weeds around well head, sep, meter house and TNK BTRY | | |
| Corrective Action: | Rule 603 f | Date: | 05/25/2020 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------------|-------|--|
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Chain like | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Chain link | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Chain link | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|-----|-------|-----------------|
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|---|--|------------------|
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter test card is out of date annual inspection has past | | |
| Corrective Action: | Measure gas per Rule 329. | | Date: 06/04/2020 |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|----------|---------|------------------|
| PRODUCED WATER | 1 | 100 BBLS | Open Top | | , |
| Comment: | Bird netting has hole | | | | |
| Corrective Action: | Repaire Net or fence pit to prevent access per rule 902.d. | | | | Date: 05/11/2020 |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|-------------|
| | | | | |
| Comment: | shares containment with crude oil tank. | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |

Inspected Facilities

Facility ID: 256027 Type: WELL API Number: 001-09396 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Monday May 4, 2020 at approximately 11:40AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Gaspar 11-1</p> <p>Operator: PetroShare Corporation</p> <p>API#:05-001-09396</p> <p>County: Adams</p> <p>While there, I observed Well site and production facility</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Debris: Rule 603f Corrective action date of 5-25-20 see photos 2,3,4,6,8</p> <p>Wildlife protection: Rule 902 d Corrective action date of 5-11-20 See photo 7</p> <p>Meter test card: Rule 329 Corrective action date of 6-4-20</p> <p>Weather conditions: Clear and location dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | silverr | 05/04/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 693502854 | loc pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5140571 |