

# Inspection Photos

5/04/2020

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335275

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335275



**Photo 1:** Photo taken from the Location, facing north. Photo shows the active wells on the Location.



**Photo 2:** Photo taken from the Location, facing northeast. Photo shows the active wells on the Location.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335275



**Photo 3:** Photo taken from the west end of the Location, facing south. Photo shows sediment trap; Trap appears to have sufficient inlet/outlet armoring.



**Photo 4:** Continued from photo 3.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335275



**Photo 5:** Photo taken from the west end of the Location. Photo shows stormwater runoff has caused erosion degradation on the slopes, cutting into the hillside; Water appears to be undercutting large rocks; potential rockfall risk.



**Photo 6:** Photo taken from the stormwater diversion ditch on the northeast end of the Location. Photo shows velocity checks within ditch appear to be in proper functioning condition. Erosion degradation along areas of the ditch evident; Sediment deposition with ditch (advise maintenance).

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335275



**Photo 7:** See comments under photo 6.



**Photo 8:** Photo of culvert on the northeast end of the Location.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335275



**Photo 9:** Photo taken from the slopes on the east end of the Location, facing west. Photo shows areas where Operator appears to have pushed soils upon a hillside of the Location. Photo shows slopes have not been stabilized and erosion degradation is evident



**Photo 10:** Photo taken from the slopes on the east end of the Location, facing east. Photo shows areas where Operator appears to have pushed soils upon a hillside of the Location. Photo shows missing or insufficient BMPs in places on the eastern end of the soils to prevent sediment transport off location into another drainage; Photo also shows sediment deposition off Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335275



**Photo 11:** Google Earth aerial image. Photo shows areas where Operator appears to have pushed soils upon a hillside of the Location (yellow arrow). Insufficient BMPs, or BMPs missing from the slopes to prevent from erosion or sediment transport off Location. Blue arrows represent water flow direction.