

Inspection Photos
Location Name: Challenger 1-32
Location ID: 05-123-11703



COGCC Environmental Inspection
40.37558, -104.92383, 4711.4ft, 357°
05/05/2020 10:24:22 AM

Photo 1 – Separator and fiberglass produced water vault.



COGCC Environmental Inspection
40.37574, -104.92378, 4721.7ft, 84°
05/05/2020 10:26:59 AM

Photo 2 – Concrete produced water vault.

Inspection Photos
Location Name: Challenger 1-32
Location ID: 05-123-11703



Photo 3 – Challenger 1-32 wellhead



Photo 4 – Wooden fence along southeastern edge of the tank battery.

Inspection Photos
Location Name: Challenger 1-32
Location ID: 05-123-11703



Photo 5 – Vegetation outside the southeast perimeter of the fence.



Photo 6 – Vegetation outside the southeast perimeter of the fence.

Inspection Photos
Location Name: Challenger 1-32
Location ID: 05-123-11703




Photo 7 – Vegetation on the northwestern side of the facility (facing northwest).

Photo 8 – Vegetation on the northwestern side of the facility (facing southwest).

Inspection Photos
Location Name: Challenger 1-32
Location ID: 05-123-11703



Photo 9 – Tank Battery

Photo 8 – Staining at NW tank.