



Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel

Overview of location of Photos



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #1 sign at location

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #2 looking west. Note berm and fence, this is a flare pit.
The pit is not permitted.

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #3 Looking North.

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #4 looking west, camera is at east side of fence to flare pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #5 flare pit, appears to be oil. Oil has been seen in this pit in the past. Pit should be closed with a Form 27.



Inspection Photos
Location 430051
ASI 081-07747
Inspection Date: 5/5/2020
All Photos taken by Kris Neidel

Photo #6 Looking west on south boundary of location.



Inspection Photos
Location 430051
ASI 081-07747
Inspection Date: 5/5/2020
All Photos taken by Kris Neidel

Photo #7 west side of flare pit.

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #8 Vertical Separator, oil staining on ground.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel

Photo #9 Oil staining at vertical separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #10 Oil staining at vertical separator.



Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel

Photo #11 9 Close-up, vertical separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel

Photo #12 3-400BBL tanks, gravel berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel

Photo #13 observed staining on ground from failed pipe, see previous inspection, 10/28/2019.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #14 Close up of spill in tank battery, see inspection 10/28/2019.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel

Photo #15 Tank close up.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel

Photo #16 Tank battery Close-up



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #17 west side of secondary containment. Looking north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #18 Assumed Stock pile of Topsoil.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #19 It is believed this is a vent for the powerplant water line from the Yampa River.

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #20 looking at location (looking southwest) from photo #19.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #21 looking south east from north of pad.



Inspection Photos
Location 430051
ASI 081-07747
Inspection Date: 5/5/2020
All Photos taken by Kris Neidel

Photo #22 looking south east from north of pad.

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #23 Pumpjack with gas drive motor.

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #24 Photo attempted to document filled rat hole, appears 12" culvert material.



Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel

Photo #25 Wellhead. Well was shut in at time of inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location 430051
ASI 081-07747
Inspection Date: 5/5/2020
All Photos taken by Kris Neidel

Photo #26 wellhead.



Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #27 unused equipment.

Inspection Photos

Location 430051

ASI 081-07747

Inspection Date: 5/5/2020

All Photos taken by Kris Neidel



Photo #28 Pumpjack drive motor.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources