

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	old meter box and wiring with a fabricated steel pipe fence around it sitting between the wells		
Corrective Action:	Comply with Rule 603.f	Date:	08/05/2020

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Ag fence x 2		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Automation		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	exposed and partially exposed at surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241932 Type: WELL API Number: 123-09723 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 282614 Type: WELL API Number: 123-23524 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 5/5/2020 at approximately 1040 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Kerr McGee 3-14 at API# 05-123-23524 in Weld County Colorado.</p> <p>While there, I observed a TA and SI well site. Form 42 (PR) Doc # 402328706 submitted on 3-2-2020. Kerr McGee 3-14 Form 42 (PR) Doc # 402328696 submitted on 3-2-2020. McCoy Phillip unit E1 A During this inspection the following possible compliance issues were observed: 603.f housekeeping: unused meter box, electrical wiring and fence around it. CA date 8-5-2020 See attached photo 5. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	05/05/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301621	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5142858