

Inspection Photos  
Operator: Hilcorp Energy  
API#: 067-08231  
Date: 5/5/2020



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass and rubber rabbitbrush.





Photo 3. View of the southern project area from the southwestern corner facing eastward.





Photo 4. View of musk thistles within the project area.



Photo 5. View of reference area comprised of sagebrush shrubland with understory dominated by western wheatgrass, sand dropseed, and blue grama.