

NEW ELK 25-04 API# 05-071-09535 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102765



PHOTO 1: THE AUTOMATION POLE LAYING ON THE GROUND WAS REMOVED FROM THE LOCATION.

NEW ELK 25-04 API# 05-071-09535 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102765



PHOTO 2: THE IMPACTED SOIL/GRAVEL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED FROM LOCATION. MAINTENANCE WAS CONDUCTED ON THE LIQUID RING COMPRESSOR TO STOP THE LEAK.

NEW ELK 25-04 API# 05-071-09535 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102765



PHOTO 3: THE DISCARDED MATERIAL FOUND INSIDE OF THE SOUND WALLS WERE COLLECTED AND REMOVED FROM THE LOCATION.

NEW ELK 25-04 API# 05-071-09535 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102765



PHOTO 4: THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT OF THE LIQUID RING COMPRESSOR AND THE SKID WAS CLEANED.