

Inspection Photos
Operator: BP America
API#: 067-06566
Date: 5/5/2020



Photo 1. View of the project area from the northwestern corner facing center. Electrical cover is knocked down and needs to be repaired.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and intermediate wheatgrass.



Photo 3/4. View of the western project area from the southwestern corner facing northward.



Photo 5. View of reference area comprised of mixed grasses such as smooth brome and western wheatgrass.