

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2020

Submitted Date:

05/07/2020

Document Number:

699801056

FIELD INSPECTION FORMLoc ID 312704 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , Laramie | | cogccnotifications@laramie-energy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 274696 | WELL | PR | 06/18/2005 | GW | 077-08836 | WERNE 14-12 (BL-14-9- | PR |

General Comment:**COGCC Inspection Report Summary**

On Thursday 5/7/20 at approximately 10:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC BCU /14L Pad, Location #312704 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: 1000 gallon tank not properly labeled. See photo #1138 with a corrective action date of 8/7/20. Unused equipment by separator. See photo #1137 with a corrective action date of 8/7/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

| Location | | | |
|--|---|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | 1000 gallon tank not properly labeled. See photo #1138 | | |
| Corrective Action: | All tanks with a capacity of ten (10) barrels or greater shall be labeled with name of operator and operator's emergency contact telephone number. Properly label tank. | | Date: 08/07/2020 |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment by separator. See photo #1137 | | |
| Corrective Action: | Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused equipment from location. | | Date: 08/07/2020 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: _____ | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Livestock panels | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Plunger Lift | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |

| | | | |
|-----------------------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL | 1 | 1000 GAL | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-------------------------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Centralized containment | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-------------------------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Centralized containment | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|----------|----|--|
| Yes/No | NO | |
| Comment: | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-----------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 274696 | Type: | WELL | API Number: | 077-08836 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | Producing | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | | | | | | |
| Gravel | | | | | | |
| | | Compaction | | | | |
| | | Culverts | | | | |
| | | Ditches | | | | |
| Compaction | | | | | | |
| Ditches | | | | | | |
| | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 699801057 | Photos for Insp. #699801056 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145249 |