

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2020

Submitted Date:

05/08/2020

Document Number:

700700659**FIELD INSPECTION FORM**Loc ID 335304 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259709	WELL	PR	03/21/2002	GW	045-07765	CLOUGH RMV 143-18	PR
272639	WELL	PR	03/08/2005	GW	045-10108	CLOUGH RWF 434-18	PR
272641	WELL	PR	11/01/2017	GW	045-10107	CLOUGH RWF 533-18	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 5/8/20 at approximately 11:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 434-18, at Location # 335304 in Garfield Colorado.

While there, I observed normal production operations. No evidence of frack tanks on location.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	Date:	
Corrective Action:			

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 3		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 259709	Type: WELL	API Number: 045-07765	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 272639	Type: WELL	API Number: 045-10108	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 272641	Type: WELL	API Number: 045-10107	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Drains				
Ditches		Ditches				
Hydro Mulch		Waddles				
Berms		Culverts				
Seeding						

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT
Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700665	Photos for RWF 434-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146128