

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/01/2020

Submitted Date:

05/04/2020

Document Number:

700700611

FIELD INSPECTION FORM
 Loc ID 335281 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		scollett@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211391	WELL	PR	08/08/2000	GW	045-07151	GIBSON GULCH UNIT 1-30	PR
263754	WELL	PR	03/01/2011	GW	045-08137	GIBSON GULCH UNIT 2-30	PR
284608	WELL	PR	05/10/2007	GW	045-12218	GGU DALEY 41B-30-691	PR
284609	WELL	PR	05/12/2007	GW	045-12217	GGU DALEY 44A-19-691	PR
300468	WELL	PR	02/16/2010	GW	045-17905	GGU DALEY 11A-29-691	PR
300469	WELL	PR	02/16/2010	GW	045-17906	GGU DALEY 12C-29-691	PR
300470	WELL	PR	02/16/2010	GW	045-17907	GGU DALEY 11D-29-691	PR
300471	WELL	PR	02/16/2010	GW	045-17908	GGU DALEY 41A-30-691	PR
300472	WELL	PR	02/16/2010	GW	045-17909	GGU DALEY 44B-19-691	PR
300473	WELL	PR	02/16/2010	GW	045-17910	GGU DALEY 41C-30-691	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 5/1/20 at approximately 2:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly GGU 1-30, at Location # 335281 in Garfield Colorado.

During this inspection the following possible compliance issues were observed:

- Staining next to tank manway

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	staining next to tank manway		
Corrective Action:	remove staining	Date:	05/15/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Type	IGNITOR/COMBUSTOR			
Comment:				
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	

Equipment:

				corrective date
Type: Bird Protectors	# 10			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 10			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 10			
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	chemical tanks			
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	OTHER	HEATED STEEL AST		,	
Comment:	three (3) 375 bbl tanks are not heated					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	YES		
--------	-----	--	--

Comment:	three (3) braden heads are open		
Corrective Action:		Date:	
Flaring:			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	211391	Type:	WELL	API Number:	045-07151	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	263754	Type:	WELL	API Number:	045-08137	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284608	Type:	WELL	API Number:	045-12218	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	284609	Type:	WELL	API Number:	045-12217	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300468	Type:	WELL	API Number:	045-17905	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300469	Type:	WELL	API Number:	045-17906	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300470	Type:	WELL	API Number:	045-17907	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300471	Type:	WELL	API Number:	045-17908	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID:	300472	Type:	WELL	API Number:	045-17909	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	300473	Type:	WELL	API Number:	045-17910	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Culverts				
		Gravel				
Gravel		Ditches				
Berms		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402389114	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5141020
700700621	photos for GGU 1-30	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5141014