

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402395679

Date Received:
05/12/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10409

Name of Operator: PEAKVIEW OPERATING COMPANY LLC

Address: 1001 17TH ST SUITE 1050

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Walters, Steve

720-402-3081

swalters@peakviewenergy.com

Wise, Wayne

720-402-3085

wwise@peakviewenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689804081

Inspection Date: 04/29/2020

FIR Submit Date: 04/29/2020

FIR Status: _____

Inspected Operator Information:

Company Name: PEAKVIEW OPERATING COMPANY LLC

Company Number: 10409

Address: 1001 17TH ST SUITE 1050

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 312913

Location Name: Kowach Number: 24-9 SWD County: MOFFAT

Qtrqr: SESW Sec: 9 Twp: 6N Range: 90W Meridian: 6

Latitude: 40.485521 Longitude: -107.499655

FACILITY - API Number: 05-081- -00 Facility ID: 222825

Facility Name: KOWACH Number: 1-9

Qtrqr: SESW Sec: 9 Twp: 6N Range: 90W Meridian: 6

Latitude: 40.485521 Longitude: -107.499655

CORRECTIVE ACTIONS:

1 CA# 138492

Corrective Action: Close and seal gauge hatches when not accessing tank per Rule 605.a.(9).

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator Comment: Thursday morning April 30th 2020, the water hauler was notified about Wednesday's open gauge hatch incident and told to keep the hatch closed when not "on location" pulling water from the water tank.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 138493

Corrective Action: Comply with Rule 603.f .
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
Properly dispose of oily waste in accordance with 907.e.

Date: 05/13/2020

Response: CA COMPLETED

Date of Completion: 05/07/2020

Operator Comment: PCC "Load Line Containment" vessel was replaced and crude oil load line connections were tightened.
Stained soil and gravel around the load lines and inside the tank battery berm was removed and hauled to Milner
Landfill for proper disposal.
Twin Enviro Services/Milner Landfill manifest and weight ticket are attached.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Twin Enviro Services/Milner Landfill documents reflect the stained soil removed from the Kowach 1-9 tank battery and the
stained gravel removed from inside the Buck Peak State 1-16 wellhead enclosure.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and
complete.

Print Name: Wayne Wise

Signed: _____

Title: Operations Engineer

Date: 5/12/2020 3:39:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document
Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402395729	Kowach 1-9 Stained Soil Disposal Document
402395730	Kowach 1-9 Stained Soil Disposal Document

Total Attach: 2 Files