

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402396560

Date Received:  
05/12/2020

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: <u>10409</u>	Contact Name and Telephone:
Name of Operator: <u>PEAKVIEW OPERATING COMPANY LLC</u>	Name: _____
Address: <u>1001 17TH ST SUITE 1050</u>	Phone: ( ) _____ Fax: ( ) _____
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>	Email: _____

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Walters, Steve</u>	<u>720-402-3081</u>	<u>swalters@peakviewenergy.com</u>
<u>Wise, Wayne</u>	<u>720-402-3085</u>	<u>wwise@peakviewenergy.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 689804073  
 Inspection Date: 04/29/2020 FIR Submit Date: 04/29/2020 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: PEAKVIEW OPERATING COMPANY LLC Company Number: 10409  
 Address: 1001 17TH ST SUITE 1050  
 City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 312911

Location Name: BUCK PEAK STATE-66N90W Number: 16SWNE County: MOFFAT  
 Qtrqtr: SWNE Sec: 16 Twp: 6N Range: 90W Meridian: 6  
 Latitude: 40.479043 Longitude: -107.493367

### FACILITY - API Number: 05-081-00 Facility ID: 222818

Facility Name: BUCK PEAK STATE Number: 1-16  
 Qtrqtr: SWNE Sec: 16 Twp: 6N Range: 90W Meridian: 6  
 Latitude: 40.479043 Longitude: -107.493367

### CORRECTIVE ACTION:

1 CA# 138488

Corrective Action: Comply with Rule 603.f . Date: 05/13/2020

Response: CA COMPLETED Date of Completion: 05/07/2020

Operator Comment: Surplus equipment and unused supplies were removed from the wellhead enclosure/house.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 138489

Corrective Action: Comply with Rule 603.f .  
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,  
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.  
Properly dispose of oily waste in accordance with 907.e.

Date: 05/13/2020

Response: CA COMPLETED

Date of Completion: 05/07/2020

Operator Comment: Stained soil and gravel around the wellhead, was removed and hauled to the Milner Landfill for proper disposal.  
Twin Enviro Services/Milner Landfill manifest and weight ticket are attached.  
Wellhead piping and fittings were cheked for integrity.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Twin Enviro Services/Milner Landfill documents reflect the stained soil and gravel removed from inside the Buck Peak State 1-16 wellhead enclosure and stained soil removed from the Kowach 1-9 tank battery.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Wayne Wise

Signed: \_\_\_\_\_

Title: Operations Engineer

Date: 5/12/2020 7:33:14 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402396562	Buck Peak State 1-16 Stained Soil Disposal Documents
402396563	Buck Peak State 1-16 Stained Soil Disposal Documents

Total Attach: 2 Files