

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2020

Submitted Date:

05/13/2020

Document Number:

697001264

FIELD INSPECTION FORMLoc ID 307073 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 95233

Name of Operator: WELLINGTON OPERATING COMPANY

Address: 6065 S QUEBEC ST STE 200

City: CENTENNIAL State: CO Zip: 80111

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pomeroy, Bradley		pomoco@msn.com	
Gracey, Cameron		graceyservices@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216755	WELL	PR	08/01/1993	OW	069-05182	W F MUDDY UT/MITCHELL 14-1	SI

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical systems		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:		
Type	PUMP JACK	
Comment:	Panel	
Corrective Action:		Date:

Equipment:			corrective date
Type: Vertical Heater Treater	# 1		
Comment:	60 bbls heater treater. Inadequate berms around tank.		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).		Date: <u>07/17/2020</u>
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:	60 bbls separator. Inadequate berms around tank.		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).		Date: <u>07/17/2020</u>

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas engine		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	500 BBLs	STEEL AST		,
Comment:	Overflow tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Inadequate berms around tank. See attached photos.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 07/17/2020

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Inadequate berms around tank. See attached photos.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 07/17/2020

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Inadequate berms around tank. See attached photos.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			
			Date:	07/17/2020

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Inadequate berms around tanks. See attached photos.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			
			Date:	07/17/2020

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	216755	Type:	WELL	API Number:	069-05182	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697001265	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5149417