

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2020

Submitted Date:

05/13/2020

Document Number:

699301705**FIELD INSPECTION FORM**Loc ID 430669 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430666	WELL	PR	10/01/2019	OW	123-36245	SPARBOE 1N-26HZX	PR
430670	WELL	SI	01/01/2020	OW	123-36248	SPARBOE 26C-26HZ	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate x 2		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	AG fence x 2		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Transformers and electric panel- AG fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 3		
Comment:	electric panel, transformer and automation		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 430666 Type: WELL API Number: 123-36245 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 430670 Type: WELL API Number: 123-36248 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since 1-1-2020

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/13/2020 at approximately 1020 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: right;">Sparboe 1N-26HZ at Location</p> <p>#430669 in Weld County Colorado.</p> <p>While there, I observed a multi well wellsite. Sparboe 1N-26HzX is PR, the Sparboe 26C-26Hz is SI since 1-1-2020.</p> <p>During this inspection no compliance issue was observed:</p> <p>See attached photos.</p> <p>Location is dry, weather is cloudy.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	05/13/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301706	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5149526