

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/29/2020

Submitted Date:

05/08/2020

Document Number:

689501024**FIELD INSPECTION FORM**Loc ID 322024 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 17320Name of Operator: CITY & COUNTY OF DENVERAddress: 8500 PENA BLVD CONCOUR A #4385City: DENVER State: CO Zip: 80249**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Branting, Julie	303-638-7484	Petropro@comcast.net	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208822	WELL	SI	06/01/2018	OW	031-06418	KALLSEN 5	EI

**General Comment:**

This is an environmental inspection of spill document #2146882 reported 11/8/2013 -spill remains open in COGCC database. No surface impacts were observed in the spill area. Operator is directed to contact the Area EPS regarding spill closure.

Photos attached to document location at time of inspection.

Any corrective actions from previous inspections that have not been addressed are still applicable.



**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: COGCC Spill Document #2146882 (reported 11/8/2013) remains open in the COGCC database. Spill documents reports that the spill occurred from a flowline just east of the Kallsen 5 well. No surface impacts were observed in this area (photo 2).

Corrective Action: Contact COGCC EPS Kari Oakman regarding spill closure. - Kari.oakman@state.co.us - 720-355-3135

Date: 06/13/2020

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402393677	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145759">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145759</a>
689501025	Location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145750">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145750</a>