

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2020

Submitted Date:

05/14/2020

Document Number:

699801100

**FIELD INSPECTION FORM**Loc ID 312472 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
, Engineering		dnr_cogccengineering@state.co.us	
Graves, Jim		mrinc20@maralexinc.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221715	WELL	SI	09/01/2017	GW	077-08317	LATHAM 18-1	SI

**General Comment:****COGCC Inspection Report Summary**

On Thursday 5/14/20 at approximately 12:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC LATHAM-68S99W /18SENW, Location #312472 in Mesa County Colorado.

Refer to document #693801059 inspection conducted on 8/28/19. Not all previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Multiple places with debris on location. See photo #1189 and #1190 with a corrective action date of 5/28/20. Gas leaking past tubing hanger flange on wellhead. With a previous corrective action date of 8/31/19. MIT required on well. With a corrective action date of 8/14/20. No pit permit on record. With a corrective action date of 6/14/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Multiple places with debris on location. See photo #1189 and #1190			
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.			Date: 05/28/2020
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PIT			
Comment:	Hog panels			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Bird Protectors	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				

Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	YES		
Comment:	Gas leaking past tubing hanger flange on wellhead.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition.	Date:	08/31/2019
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 221715 Type: WELL API Number: 077-08317 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last produced August 2017. No MIT on record.Corrective Action: A mechanical integrity test shall be performed on each shut-in well within two years of the initial shut-in date. Preform MIT on well.Date: 08/14/2020

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction						
		Ditches				
		Culverts				
		Gravel				
		Compaction				
Ditches						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: No pit permit on record.Corrective Action: Submit an eForm 15 Pit Report to update COGCC records with current information.Date: 06/14/2020**Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: MeshNetting Condition: Comment: Corrective Action: Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801101	Photos for Insp. #699801100	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151388">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151388</a>