

# Inspection Photos

API: 041-06067

Operator: ULTRA RESOURCES INC

Inspection Date: 5/13/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 041-06067 | Date: 5/13/2020

## Inspection Photos



**Photo 1.** Facing west toward the reclaimed access road. The vegetation has uniformly established along the reclaimed road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06067 | Date: 5/13/2020

## Inspection Photos



**Photo 2.** The perimeter fence remains around the location and needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06067 | Date: 5/13/2020

## Inspection Photos



**Photo 3.** Facing southwest toward the location. The vegetation has uniformly established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06067 | Date: 5/13/2020

## Inspection Photos



**Photo 4.** Facing south at the location. The perimeter fence remains around the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06067 | Date: 5/13/2020

## Inspection Photos



**Photo 5.** The degraded wattles remain at the location. The plastic netting and stakes need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06067 | Date: 5/13/2020

## Inspection Photos



**Photo 6.** The degraded wattles remain at the location. The plastic netting and stakes need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06067 | Date: 5/13/2020

## Inspection Photos



**Photo 7.** Facing northwest toward the location. The vegetation has uniformly established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06067 | Date: 5/13/2020