



40.19978, -107.46431, 8120.0ft, 318°
05/14/2020 10:45:06 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Pump jack & propane tanks.

McSullivan NCT-1 #1

API: 05-103-09258

Inspection: 700401481





40.19965, -107.46565, 8127.4ft, 264°
05/14/2020 10:53:20 AM



40.19955, -107.46592, 8123.6ft, 332°
05/14/2020 10:53:59 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

McSullivan NCT-1 #1

API: 05-103-09258

Inspection: 700401481



40.19949, -107.46636, 8123.6ft, 275°
05/14/2020 10:55:55 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Separator.

McSullivan NCT-1 #1

API: 05-103-09258

Inspection: 700401481



40.20011, -107.46599, 8093.9ft, 166°
05/14/2020 10:39:50 AM



40.19954, -107.46658, 8120.9ft, 69°
05/14/2020 10:57:35 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Pump jack at motor end.

McSullivan NCT-1 #1

API: 05-103-09258

Inspection: 700401481



40.20017, -107.46454, 8100.5ft, 221°
05/14/2020 10:48:11 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. Side of pump jack.

McSullivan NCT-1 #1

API: 05-103-09258

Inspection: 700401481



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 10. Recent dirt added.

McSullivan NCT-1 #1

API: 05-103-09258

Inspection: 700401481



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 11. Well head.

McSullivan NCT-1 #1

API: 05-103-09258

Inspection: 700401481



40.20016, -107.4645, 8103.9ft, 257°
05/14/2020 10:50:12 AM