



40.20103, -107.47265, 8057.9ft, 305°
05/14/2020 11:06:44 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Seely Land & Livestock 1 API: 05-103-09250
Inspection: 700401483



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Seely Land & Livestock 1 API: 05-103-09250
Inspection: 700401483



40.20125, -107.47311, 8044.0ft, 297°
05/14/2020 11:13:40 AM



40.20129, -107.47264, 8055.3ft, 262°
05/14/2020 11:07:41 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Treater.

Seely Land & Livestock 1 API: 05-103-09250
Inspection: 700401483



40.20142, -107.47278, 8051.3ft, 307°
05/14/2020 11:08:07 AM



40.20153, -107.4728, 8052.8ft, 247°
05/14/2020 11:08:38 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Inside building viewed through window.

Seely Land & Livestock 1 API: 05-103-09250
Inspection: 700401483



40.2013, -107.47318, 8053.9ft, 0°
05/14/2020 11:09:41 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Chemical containers.

Seely Land & Livestock 1 API: 05-103-09250
Inspection: 700401483



40.20123, -107.47324, 8037.5ft, 78°
05/14/2020 11:14:59 AM



40.20121, -107.47331, 8053.1ft, 11°
05/14/2020 11:15:13 AM



40.20125, -107.4732, 8056.6ft, 196°
05/14/2020 11:14:40 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 11. Side of pump jack. Oil on ground partially covered by recent dirt.

Seely Land & Livestock 1 API: 05-103-09250
Inspection: 700401483



40.20125, -107.47321, 8060.2ft, 204°
05/14/2020 11:14:24 AM



40.20119, -107.47321, 8060.4ft, 340°
05/14/2020 11:15:35 AM