

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2020

Submitted Date:

05/11/2020

Document Number:

689704664

FIELD INSPECTION FORMLoc ID 322527 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10341

Name of Operator: PUCKETT LAND COMPANY

Address: 5460 S. QUEBEC STREET - STE #250

City: GREENWOOD State: CO Zip: 80111

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Stearns, Eric		ericstearns@puckettland.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Burger, Craig		craig.burger@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210721	WELL	SI	01/01/2018	GW	045-06479	CATHEDRAL CREEK 2	SI

General Comment:

I, Inspector Mike Longworth, conducted an inspection on site.

During this inspection the following possible compliance issues were observed:

No current Mechanical Integrity Test (MIT) on record as required by Rule 326

Perform MIT per Rule 326 a. (1)

Date: 07/11/2020

No label on chemical container at well.

Corrective Action: Install sign to comply with Rule 210.d.

Date: 08/11/2020

Tank labels are the previous operator's. No tank capacity on tank labels.

Corrective Action: Install sign to comply with Rule 210.d.

Date: 08/11/2020

Previous operator sign is at intersection of main road and access road.

Corrective Action: Install sign to comply with Rule 210.e.

Date: 08/11/2020

Marker is down on 1 of the deadmen.

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 05/30/2020

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:	No label on chemical container at well.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/11/2020
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels are the previous operator's. No tank capacity on tank labels.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/11/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Previous operator sign is at intersection of main road and access road.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/11/2020

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	Maker is down on 1 of the deadmen.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	05/30/2020

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical container at well.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210721 Type: WELL API Number: 045-06479 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: No current Mechanical Integrity Test (MIT) on record as required by Rule 326Corrective Action: Perform MIT per Rule 326 a. (1)Date: 07/11/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402394558	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146517
689704680	Inspection 689704664 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146516