

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/28/2020

Submitted Date:

04/28/2020

Document Number:

699501196

FIELD INSPECTION FORM

Loc ID 320156 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 19035
Name of Operator: OVERLAND RESOURCES LLC
Address: SUITE C18 PMB 440
City: GREENWOOD State: CO Zip: 80121

Findings:

- 11 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Pandolfo, Chris	(650) 387-6506	cpandolfo@gmail.com	
,		dnr_cogccenforcement@state.co.us	
Anderson, Robert	303-800-6175	admin@overlandresourcesllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202852	WELL	SI	07/01/2017	OW	001-08257	THOMPSON-PRICE 2	SI

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	No Sign or label on water tank see pics		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/26/2018
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/14/2017

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Soiled dirt around Produced water tanks (fiberglass and steel). Stained soil under load out line to produced water tank (steel).		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	04/14/2017
Type	OTHER		
Comment:	Stained soil around pumping unit motor and gear box see pics		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	04/14/2017
Type	OTHER		
Comment:	Stained soil possible leak in seperator house see pic 9		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	06/07/2019
Type	OTHER		
Comment:	Inadequate berms around tank(s)		
Corrective Action:	n: Repair or install berms or other secondary containment devices per Rule 605.a.(4).	Date:	11/26/2018

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	gas motor		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	inadequate			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	inadequate berms			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: <u>202852</u>	Type: <u>WELL</u>	API Number: <u>001-08257</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <input style="width: 80%;" type="text" value="SI"/>				
Corrective Action: <input style="width: 80%;" type="text"/>				Date: _____

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 4/28/2020 at approximately 1200 I, Inspector Justin Medina conducted an onsite inspection at Thompson Price #2 Overland Resources LLC 001-08257 in Adams County Colorado.</p> <p>While there, I observed Shut in well This is a follow up inspection from document # 685502197 & 688400480 & 685100925 All Corrective Actions from previous 3 inspections have not been addressed and are delinquent as of 10/24/18 Location is not accessible during normal business hours. Provide key, combinations, or alternate method of access to comply with rule 204. Sign or label not posted or information inaccurate on tanks or containers No placards on Pro Water fiberglass tank Install sign to comply with Rule 210.d. Stained soil around PU motor and gear box Properly treat or dispose of oily waste in accordance with 907.e. Soiled dirt around Produced water tanks (fiberglass and steel). Stained soil under load out line to produced water tank (steel). Properly treat or dispose of oily waste in accordance with 907.e. Stained soil possible leak in seperator house see pic 9 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 6/7/19 Inadequate berms around tank(s) Repair or install berms or other secondary containment devices per Rule 605.a.(4). Inadequate berms around tank(s) Repair or install berms or other sec</p>	medinaj	04/28/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402395007	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146860
699501197	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146847