

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2020

Submitted Date:

05/18/2020

Document Number:

689804149**FIELD INSPECTION FORM**Loc ID 416625 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name         | Phone | Email  | Comment                         |
|----------------------|-------|--|---------------------------------|
| Colby, Lou           |       | lou.colby@state.co.us                          |                                 |
| Inspections, General |       | sandridgeenvironmental@san<br>dridgeenergy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 298842      | WELL | PR     | 02/10/2017  | OW         | 057-06480 | Surprise 4-06H | SI          |
| 298844      | WELL | PR     | 11/20/2013  | OW         | 057-06482 | DAMFINO 2-06H  | SI          |

**General Comment:**[Routine FIU inspection.](#)

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 405-429-5974

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                             |       |            |
|--------------------|-----------------------------|-------|------------|
| Type               | WEEDS                       |       |            |
| Comment:           | Weeds growing on fill pile. |       |            |
| Corrective Action: | Comply with Rule 603.f .    | Date: | 06/01/2020 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                               |     |       |                 |
|-------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>             |     |       | corrective date |
| Type: Bird Protectors         | #   |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Flare                   | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Emission Control Device | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Pump Jack               | # 2 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Gas Meter Run           | # 1 |       |                 |

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 2 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| PRODUCED WATER     | 2 | 400 BBLs | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| CRUDE OIL          | 7 | 400 BBLs | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |

**Venting:**

|                    |    |  |  |
|--------------------|----|--|--|
| Yes/No             | NO |  |  |
| Comment:           |    |  |  |
| Corrective Action: |    |  |  |

**Flaring:**

|      |  |  |
|------|--|--|
| Type |  |  |
|------|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**Facility ID: 298842 Type: WELL API Number: 057-06480 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_Facility ID: 298844 Type: WELL API Number: 057-06482 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Fail            |                         |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |
| Silt Fences      | Fail            |                         |                       |               |                          |         |

Comment: Location cut slopes are collapsing into location. Silt fence above cut slope is not preventing this. Erosion occurring on fill pile, no BMP on southeastern side of pile.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/08/2020

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 689804169    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152993">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152993</a> |