

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2020

Submitted Date:

05/18/2020

Document Number:

688800733

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 Hughes, Jim _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 1199 MAIN AVENUE SUITE 101
 City: DURANGO State: CO Zip: 81301
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268987	WELL	PR	01/01/2018	GW	067-08810	MCCAW C 2	EI
476264	SPILL OR RELEASE	AC			-	McCaw C 2	EI

General Comment:

On May 7, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #476264. For the most recent field inspection report of the McCaw C #2, please refer to document #693900133. For more information regarding Spill/Release Point ID #476264, please refer to document #402394317.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Produced Water	Separator	>= 5 bbls	
Comment:	Please refer to Initial Form 19 Document #402394317.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 06/18/2020

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Stock panel fencing around separator, telemetry equipment, meter run, and PBV.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Stock panel fencing.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Operating at the time of this inspection.		
Corrective Action:			Date:

Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.161331,-107.728131
Comment:	Paint is peeling off of PBV.				
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 268987 Type: WELL API Number: 067-08810 Status: PR Insp. Status: EI

Facility ID: 476264 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On May 7, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #476264. For the most recent field inspection report of the McCaw C #2, please refer to document #693900133. For more information regarding Spill/Release Point ID #476264, please refer to document #402394317. During this inspection, stained gravel was observed near the separator.	hughesjo	05/18/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800734	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153388