



## Form Information

|                      |  |
|----------------------|--|
| Form Name:           | <b>Compliance Follow Up Form</b>   |
| Submitter Name:      | Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)                                    |
| Submission Date:     | May 13, 2020 3:00:34 PM MDT  |
| Server Receive Date: | May 13, 2020 3:01:04 PM MDT  |
| Reference Number:    | 20200513-18142075978   |
| Location:            | Arrow St, Ignacio, CO 81137, USA<br>May 13, 2020 2:58:59 PM MDT [ <a href="#">View Map</a> ] |

## Information

|                 |   |
|-----------------|---|
| Name            | kenneth.canterbury@crossfire-llc.com                                      |
| Date            | May 5, 2020   |
| Well Name       | UTE GAS UNIT AC 2   |
| API Number      | 50670881200   |
| Select State    | Colorado  |
| Work type       | BLM Inspection AR   |
| Action Complete | Compliance Inspection Actions<br>Erosion Repairs<br>Install Rock Run Down |

## Photo of first corrective action completed



## Completed work description Corrective Action 1

## Compliance

## Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed



Installed diversion ditch

Completed work description of corrective action 3

Photo of fourth corrective action completed



Cleaned up location

Completed work description

Completed work description of corrective action 4

Summary of all work completed

Installed rock run down

Cleaned up location

Compliance, installed diversion ditch, cleaned up location and installed rock run downs