

Inspection Photos  
Operator: Petrox  
API#: 007-06269  
Date: 5/15/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the northern project berm with early season weeds becoming established. Needs to be stabilized with desirable perennial vegetation or otherwise stabilized. Short term stormwater controls are needed until stabilized with desirable vegetation.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Outer berms are weed infested.



Photo 4. Closeup view of spotted knapweed within the project area with inflorescence from previous growing season.



Photo 5. View of dense Canada thistles within the western project area, revegetation berm.



Photo 6. View of dense musk thistles observed within the outer reclamation berm.



Photo 7. View of reference area vegetation . Location is on the edge of an irrigated grass field, and outside of irrigation alignment.