

Inspection Photos

API: 071-07516

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/18/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 1. Facing west along the access road crossing the ephemeral drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 2. Facing north along the access road. There is an erosion channel that has developed overtopping water bar shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 3. Facing northeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 4. Facing north along the access road. Cattle guard remains in place and is maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 5. Facing back toward the south near the cattleguard. The road crossing near the drainage will require BMP maintenance. The rock rip rap has been washed out in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 6. View of rock rip/rap that has been displaced will need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 7. Facing northwest toward reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 8. The perimeter fence remains around location and needs maintenance in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 9. Facing northwest toward the location. The vegetation is uniformly established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 10. Facing west toward the location. The vegetation is uniformly established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020

Inspection Photos



Photo 11. Facing south toward the location. The vegetation is uniformly established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07516 | Date: 5/18/2020