

Inspection Photos
Operator: Southland Royalty
API#: 007-06211
Date: 5/15/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of cement debris located on the western edge of the project area.



Photo 3. View of area on southern fill slope where sediment trap was breached and is repaired. Area is replaced with soil, and appears to have been seeded. Wattles in place as secondary containment are not installed properly as they are not trenched into soil.



Photo 4. View of area where erosion is occurring where culvert crosses the access road near the well pad entrance. Additional stabilization is needed here.



Photo 5. View of reference area vegetation comprised of pinyon juniper woodland with understory of grasses and forbs such as Indian ricegrass, James galleta, and Navajo tea.