

Crestone Peak Resources - COGCC Inspection Photos

Well: Costigan 34-20

API # 123-30058 Date 5/20/2020



Signage at out of service flowline riser.



View from Costigan 34-20 PA wellhead flowline riser to facility;
on location flowline/ looking east.

Crestone Peak Resources - COGCC Inspection Photos

Well: Costigan 34-20

API # 123-30058 Date 5/20/2020



Close up view of inactive flowline riser; Open ended/ Not bull plugged. No OOSLAT in place.



Inactive flowline riser at inlet to heated horizontal separator
No OOSLAT in place

Crestone Peak Resources - COGCC Inspection Photos

Well: Costigan 34-20

API # 123-30058 Date 5/20/2020



**Close up view of inactive flowline riser at separator
No OOSLAT in place.**



**Out of service flowline risers at horizontal separator;
Unused equipment, No LO/TO (OOSLAT)**