

Inspection Photos
Operator: BP America
API#: 067-08378
Date: 5/20/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass, sand dropseed, and smooth brome.



Photo 3. View of the northeastern cut-slope. Revegetation is progressing here with blue gramma and *Heterotheca villosa*.



Photo 4. View of the northern cut-slope. Vegetation is not increasing significantly. Bare soils need stabilization.



Photo 5. View of the northwestern cut-slope. Bare soils need stabilization.



Photo 6. View of reference area vegetation comprised of pinyon juniper woodland with understory of gambel oak, black sage, muttongrass, and penstemon.