



<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers No placards on Crude tanks, Pro Water tank, or Pump Jack		
Corrective Action:	Install sign to comply with Rule 210.d. Corrective action Date 6/15/2020 see photo# 1 & 4	Date:	06/15/2020
Type	WELLHEAD		
Comment:	Sign or label not posted or information inaccurate on tanks or containers No placards on Crude tanks, Pro Water tank, or Pump Jack		
Corrective Action:	Install sign to comply with Rule 210.d. Corrective action Date 6/15/2020 see photo# 1 & 4	Date:	06/15/2020
Type	BATTERY		
Comment:	Sign or label not posted or information inaccurate on tanks or containers No placards on Crude tanks, Pro Water tank, or Pump Jack		
Corrective Action:	Install sign to comply with Rule 210.d. Corrective action Date 6/15/2020 see photo# 1 & 4	Date:	06/15/2020
<b>Emergency Contact Number:</b>			
Comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:	Stained soil around Pump Jack motor and gear box.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e. Corrective action Date 6/15/2020, see photo# 7	Date:	06/15/2020
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		
Comment:	Soiled soil around Produced water tanks. Stained soil under load out line to produced water tank.				
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e. Corrective action Date 6/15/2020, see photo# 2				Date: 06/15/2020

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Shares berm with crude tanks			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4). Inadequate berms around tank(s) Corrective action Date 6/15/2020, see photo# 1 & 4			Date: 06/15/2020

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.811432,-104.207511
Comment:	Soiled soil around Produced water tanks. Stained soil under load out line to produced water tank. Bull plug missing from loadoff line.				
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e. Corrective action Date 6/15/2020, see photo# 2 Location is within a designated setback location, bullplug or cap all loadlines per Rule #604.c.(2)O. Corrective action Date 5/25/2020, see photo# 3				Date: 06/15/2020

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate

Comment:	Inadequate berms around tank(s), and separator		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4). Inadequate berms around tank(s) Corrective action Date 6/15/2020, see photo# 1 & 4	Date:	<u>06/15/2020</u>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 202852 Type: WELL API Number: 001-08257 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday May 12, 2020 at approximately 10:00 am I, Inspector Chane Finkenbinder conducted an onsite inspection at the Thompson Price #2 Overland Resources LLC 001-08257 in Adams County Colorado.                      While there, I observed Shut in well</p> <p>Sign or label not posted or information inaccurate on tanks or containers                      No placards on Crude tanks, Pro Water tank, or Pump Jack                      Install sign to comply with Rule 210.d. Corrective action Date 6/15/2020 see photo# 1 &amp; 4</p> <p>Stained soil around Pump Jack motor and gear box                      Properly treat or dispose of oily waste in accordance with 907.e. Corrective action Date 6/15/2020, see photo# 7</p> <p>Soiled soil around Produced water tanks. Stained soil under load out line to produced water tank. Properly treat or dispose of oily waste in accordance with 907.e. Corrective action Date 6/15/2020, see photo# 2</p> <p>Bull plug missing from loadoff line. Location is within a designated setback location, bullplug or cap all loadlines per Rule #604.c.(2)O. Corrective action Date 5/25/2020 , see photo# 3                      Inadequate berms around tank(s)                      Repair or install berms or other secondary containment devices per Rule 605.a.(4).                      Inadequate berms around tank(s) Corrective action Date 6/15/2020, see photo# 1 &amp; 4</p> <p>Repair or install berms or other secondary containment devices per Rule 605.a.(4).                      Corrective action Date 6/15/2020, see photo# 6</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	finkenbc	05/19/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402402269	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154581">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154581</a>
700900084	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154577">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154577</a>