

Inspection Photos
Operator: BP America
API#: 067-06546
Date: 5/20/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing on the slope with grasses such as western wheatgrass and smooth brome, as well as shrubs such as rubber rabbitbrush.



Photo 3. View of equipment that is not in use, near the wellhead.



Photo 4. View of stained soils around the wellhead.



Photo 5. View of unused fencing materials within the western project area.



Photo 6. View of reference area vegetation comprised of pinyon-juniper woodland with understory of gambel oak, black sage, and mutton grass.