

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2020

Submitted Date:

05/26/2020

Document Number:

699301815

FIELD INSPECTION FORM

Loc ID 430972 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430973	WELL	PR	06/01/2019	GW	123-36362	POWERS 4C-27HZ	PR
430974	WELL	PR	09/01/2018	GW	123-36363	POWERS 4N-27HZ	PR
430975	WELL	PR	04/01/2019	OW	123-36364	POWERS 30N-27HZ	PR
430976	WELL	PR	10/01/2017	OW	123-36365	POWERS 30C-27HZ	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	AG fence x 4		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electric panels also have AG fence		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	automation and electric panels		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	430973	Type:	WELL	API Number:	123-36362	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	430974	Type:	WELL	API Number:	123-36363	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	430975	Type:	WELL	API Number:	123-36364	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	430976	Type:	WELL	API Number:	123-36365	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR							Date:	
Corrective Action:								Date:	

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 5/26/2020 at approximately 1425 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Powers 30N-27HZ at Location</p> <p>#430972 in Weld County Colorado. While there, I observed a producing multi well pad. During this inspection no compliance issues were observed: See attached photos. Location is partially dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	05/26/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301816	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5159196